

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 17 November 2016
Australia – Victoria

No. 325(T) - 2016

Port of Port Phillip

Brighton
R2 Recreation Buoy - Missing

Date: Immediate.

Details: Mariners are advised that the R2 recreational buoy with characteristics Fl.(3)Y.10s and positioned at approximate location 37°54.535'S, 144°56.336'E (WGS84) is missing.

The buoy will be reinstated once weather conditions are suitable.

Mariners are advised to navigate with caution within the vicinity of the missing buoy.

Charts & Publications

Affected: AUS 143 & 155

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963

Cathy Jenkins
A/Senior Manager Local Ports and Waterways
Melbourne Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.