

Melbourne, 15 November 2016

AUSTRALIA – VICTORIA
No. 322 (T) – 2016
PORT OF MELBOURNE – YARRA RIVER – BOLTE BRIDGE
STARBOARD HAND BEACON MISSING

Date: Effective immediately

Details: Mariners are advised the starboard hand beacon located in the vicinity of the Bolte Bridge in position 37° 49.14' S, 144° 55.91' E is missing.

A buoy with matching light characteristics FI(2)G.5s will be installed in the above position until further notice.

Mariners are advised to navigate with caution in the vicinity of the area.

Charts & Publications affected: AUS 154 & AUS 155, Admiralty List of Lights and Fog Signals NP83 (Volume K).

Further notice: Further notice to be issued.



Roy Stanbrook
Harbour Master