

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

AUSTRALIA – VICTORIA

No.321 (Permanent) of 2016

BARWON HEADS

Establishment of Cardinal Mark Buoy

Date: EFFECTIVE IMMEDIATELY

Details: Mariners are advised that a south cardinal mark buoy has been established south of the Orungal wreck.

South Cardinal Mark Buoy

Light Colour: White

Light Characteristic: Q6 +LFI W 15 s

Range: 2 M

Day mark: N/A

Buoy: Pilar

Colour Black below yellow

Location: 38° 17.276' S 144° 30.572' E

Datum WGS 84

AUS Charts and publications affected:

AUS 143

Victorian Charts and Publications affected:

Nil

Further notice:

No further notice will be issued.

PETER CORCORAN

Director Maritime Safety Victoria

18 November 2016