

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA

VICTORIA

No.005(T) OF 2017

PORT OF CORNER INLET & PORT ALBERT

PORT ALBERT ENTRANCE

FAIRWAY BUOY UNLIT

DATE: 4th January 2017 – Effective Immediately

DETAILS: Mariners are advised that the Port Albert Entrance Fairway Buoy (RW), LFI.10s, is currently unlit.

Charted Position :

Lat. 38° 43.974' S

Long. 146° 42.675' E

Datum WGS84

Gippsland Ports shall reinstate the light as soon as weather conditions permit.

Further information can be obtained by contacting Gippsland Ports Port Welshpool Office on 0356881303.

CHART AFFECTED: Aus.181,

PUBLICATIONS AFFECTED: NP14 Australia Pilot Vol 2, Vol K List of Lights.
Gippsland Ports Online Boating Guides, electronic version available at www.gippslandports.vic.gov.au

FURTHER NOTICE: A further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER**