

# NOTICE TO MARINERS

**GIPPSLAND PORTS**



The following Notice to Mariners is published for general information.

**AUSTRALIA - VICTORIA**

**NO. 080 OF 2017**

**PORT OF GIPPSLAND LAKES**

**BULLOCK ISLAND NARROWS**

**SPEED RESTRICTION AIDS TO NAVIGATION ESTABLISHED**

**DATE:** 28<sup>th</sup> February 2017 – Effective Immediately

**PREVIOUS NOTICE:** No Previous Notice.

**DETAILS:** Mariners are advised that four lit Special Mark piles (Y) and two lit Special Mark buoys (Y) have been established in the Bullock Island Narrows.

These Aids to Navigation represent 5 knot Speed Restrictions in vicinity of and through the Bullock Island Narrows.

Two lit Special Mark piles (Y) and a single lit Special mark buoy (Y) have been established at the Southern entrance to the Narrows. Two lit Special Mark piles (Y) and a single lit Special mark buoy (Y) have been established at the Northern entrance to the Narrows.

All positions refer : WGS84 Datum

No.1 Pile Light (FI Y 4s)  
Lat. 37° 53.003' South  
Long. 147° 58.379' East

Speed Limit Light Buoy (FI Y 4s)  
Lat. 37° 53.008' South  
Long. 147° 58.372' East

No.2 Pile Light (FI Y 4s)  
Lat. 37° 53.015' South  
Long. 147° 58.365' East

# NOTICE TO MARINERS

## GIPPSLAND PORTS



No.3 Pile Light (Fl Y 4s)  
Lat. 37° 52.961' South  
Long. 147° 58.216' East

Speed Limit Light Buoy (Fl Y 4s)  
Lat. 37° 52.972' South  
Long. 147° 58.210' East

No.4 Pile Light (Fl Y 4s)  
Lat. 37° 52.981' South  
Long. 147° 58.206' East

**CHART** Aus.182 – Plans in Victoria, South East Coast – Lakes Entrance.  
**AFFECTED:**

**FURTHER** No further Notice will be issued.  
**NOTICE:**

**ALAN SMITH**

**ACTING HARBOUR MASTER**