

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 1 March 2017
Australia – Victoria

No. 082– 2017

Local Port of Port Phillip

Portarlington
Portarlington Safe Harbour – Installation of Lateral Piles

Date: Immediate.

Details: Mariners are advised that four new lit lateral piles have been installed at the entrance of Portarlington Safe Harbour.

Latitude	Longitude	Function		Light Characteristics
38°06.644'S	144°39.452'E	New Pile	Lateral Mark - Green	Fl.G.6s
38°06.665'S	144°39.445'E	New Pile	Lateral Mark - Red	Fl.R.6s
38°06.633'S	144°39.401'E	New Pile	Lateral Mark - Green	Fl.G.6s
38°06.655'S	144°39.399'E	New Pile	Lateral Mark - Red	Fl.R.6s

An unmarked pile within the Harbour located at 38°06.654'S, 144°39.382'E is now identified by a lit buoy with characteristics Fl.R.5s.

Mariners are advised to navigate with caution when entering Portarlington Safe Harbour.

Charts & Publications

Affected: AUS 143, 157.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 19 63.

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.