

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 8 March 2017**  
**Australia – Victoria**

**No. 088(T) - 2017**

**Local Port of Port Phillip**

**Corio Bay**  
**RGYC Special Mark Yacht Course Buoys – Missing and Non-Operational Light**

**Date:** **Immediate**

**Details:** Mariners are advised of changes to Special Mark Yacht Course Buoys around Corio Bay.

These buoys, are used by Royal Geelong Yacht Club to define yacht course rounding marks. Course Buoy CB1 is missing from its mooring south of Avalon. Course Buoy CB2 light is non-operational.

<b>Buoy Identification</b>	<b>Latitude (WGS84)</b>	<b>Longitude (WGS84)</b>	<b>Location</b>	<b>Light Characteristics</b>
CB1 Yellow. 3 sided.	38°05.560'S	144°24.200'E	North Channel <b>MISSING</b>	Fl.Y 5s
CB2 Yellow. 3 sided.	38°07.616'S	144°24.184'E	South of Hopetoun Channel <b>LIGHT NON-OPERATIONAL</b>	Fl.Y 5s

**Mariners are advised to navigate with caution in the vicinity of the above locations.**

**Charts & Publications**

**Affected:** AUS 143, 157

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Royal Geelong Yacht Club on 03 5229 3705**

Victor Teoh  
Senior Manager Local Ports and Waterways  
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).