

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 5 June 2017
Australia – Victoria

No. 158(T) - 2017

Local Port of Port Phillip

Patterson River
Patterson River Entrance - Port Lateral Navigation Light – Intermittently Working

Date: **Immediate.**

Details: Mariners are advised that the fixed port lateral mark light with characteristics FL(3).G.5s 6M, situated on Patterson River entrance northern rock groin at approximate location 38°04.384'S, 145°07.178'E (WGS84), is intermittently working.

The light will be repaired as soon as possible.

Mariners are advised to navigate with caution within the vicinity of Patterson River entrance.

Charts & Publications

Affected: AUS 143.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.