

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 17 April 2018
Australia – Victoria

No. 146(T) – 2018

Local Port of Port Phillip

Newport
Warmies Channel - Starboard Lateral Buoy Missing

Date: **Immediate**

Details: Mariners are advised that a green unlit starboard lateral buoy normally fixed at approximate location 37°50.999'S, 144°54.094'E (WGS84) is missing from waters within the Warmies Channel.

It will be reinstated as soon as practicable weather permitting.

Mariners are advised to navigate with caution when within Warmies Channel.

Charts & Publications

Affected: AUS 143, 154 & 155.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.