



VICTORIAN NOTICE TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 17 NOVEMBER 2011

AUSTRALIA – VICTORIA

No. 133 - 2011

PORT PHILLIP

MORNINGTON PIER

CHANGE OF LIGHT CHARACTERISTICS

Date: Immediate

Details: Mariners are advised of a change to the light characteristics displayed on the outer north east end of Mornington Pier at approximate location 38° 12.694' S, 145° 2.106' E (WGS84).

The new light displays characteristics: Q(2) G 5s

Previous characteristics were: Fl 6s

Mariners are advised to proceed with caution when navigating within the vicinity.

Charts Affected: AUS 143, 158

Further Notice: No further notice will be issued

If you require any further information please contact Parks Victoria on 13 1963.

**VIN WRIGHT
ACTING REGIONAL MANAGER
BAYS & MARITIME OPERATIONS**

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.

*Healthy Parks
Healthy People*