

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 22 November 2012

Australia - Victoria

No. 170-2012

Port of Port Phillip

CORIO BAY – OUTER HARBOUR STARBOARD PILE MARK MISSING

Date: Immediate

Details: Mariners are advised that the Starboard Pile located SE of Point Wilson Bank

(known as Steamboat Pile) at approx 38° 06.680'S, 144° 30.981'E with light characteristics: Fl.G 3s is now missing and has been replaced by a temporary

Starboard Mark Buoy.

The starboard pile mark will be re-instated as soon as practicable, weather

conditions permitting.

Mariners are advised to exercise caution when navigating in the area.

Charts & Publications AUS 143, 157 **Affected**:

Further Notice:

A Further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Vin Wright
Acting Regional Manager
Bays and Maritime Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.

