

VICTORIAN NOTICES TO MARINERS

The following Notice to Mariners is published for general information.

MELBOURNE, 21 November 2014

AUSTRALIA – VICTORIA

No. 196 - 2014

PORT OF MELBOURNE

SOUTH CHANNEL – BEACON UPGRADE WORKS COMPLETED

AIS INSTALLED ON ENTRANCE BEACON & BEACON NO. 24

Date: 21 November 2014

Notice No. 095 – 2014 refers and is cancelled.

Details: Mariners are advised that South Channel beacon upgrade works have been completed. All day marks have been standardised to 1.8 m x 1.8 m, except for the following beacons which have been resized to 4 m x 2 m:

South Channel Beacon	Latitude	Longitude
Popes Eye	38°17.33 S	144°41.28 E
Entrance Beacon	38°17.70 S	144°41.15 E
No. 11	38°19.50 S	144°50.08 E
No. 19	38°20.13 S	144°54.48 E

The coordinates and light characteristics for all beacons remain unchanged.

In addition to the works, Automatic Identification Systems (AIS) has been installed and is fully operational on the following two navigational aids in the South Channel:

Navigation Aid	Real AIS Marker	Latitude	Longitude
Entrance Beacon	'Entrance Beacon'	38°17.70 S	144°41.15 E
Beacon No. 24	'SC24'	38°17.93 S	144°53.92 E

Charts & Publications affected: AUS 143, 144 & 158, Admiralty List of Lights & Fog Signals (NP83 Volume K).

Further notice: Further notice will be issued.

**ROY STANBROOK
HARBOUR MASTER**

This notice is a direction of the Harbour Master pursuant to section 232 of the Marine Safety Act 2010. The requirements of section 232(2) have been taken into account.