

NOTICE TO MARINERS

GIPPSLAND PORTS



The following Notice to Mariners is published for general information.

AUSTRALIA

VICTORIA

NOTICE TO MARINERS No.029 OF 2018

PORT OF GIPPSLAND LAKES - REEVE CHANNEL

AIDS TO NAVIGATION ESTABLISHED - AIDS TO NAVIGATION
WITHDRAWN FROM SERVICE

DATE: 22nd January 2018

DETAILS: Mariners are advised that the following Aids to Navigation have been established or withdrawn from service in Reeve Channel Gippsland Lakes;

1. Reeve Channel No 3 buoy (Q.G.) formally in position;

Lat. 37° 52.873' South

Lon. 147° 57.251' East

Datum WGS84

has been withdrawn from Service.

A new pile beacon has been established to replace No 3 buoy and will be numbered Reeve Channel No 3 (Q.G) in position

Lat. 37° 52.875' South

Lon. 147° 57.249' East

Datum WGS84

2. Reeve Channel beacon No 5 (Fl.G.4s) formally in position;

Lat. 37° 52.894' South

Lon. 147° 56.947' East

Datum WGS84

has been withdrawn from service.

A new beacon to be numbered Reeve Channel No 5 (Fl.G.4s) has been established in position;

Lat. 37° 52.919' South

Lon. 147° 57.030' East

Datum WGS84

3. Temporary buoy No 3a (Fl.G.5s) formally in position;

Lat. 37° 52.900' South

Lon. 147° 57.035' East

Datum WGS84

has been withdrawn from service

Further information is available from Gippsland Ports on 0427 610 025

CHART AFFECTED: Aus 182

NOTICE TO MARINERS

GIPPSLAND PORTS



PUBLICATIONS Gippsland Ports Online Boating Guide electronic version available at
AFFECTED: www.gippslandports.vic.gov.au/boating/waterways-online

FURTHER NOTICE: No further notice shall be issued.

CAPT. BEVIS HAYWARD
HARBOUR MASTER