

Melbourne, 23 January 2018

Australia – Victoria  
No. 034 (T) – 2018  
PORT OF MELBOURNE  
SOUTH CHANNEL BEACON 21 TEMPORARILY UNLIT

**Date:** 23 January 2018

**Refers:** NA

**Details:** Mariners are advised that, South Channel Beacon 21 (K2323-35) in position 38° 19.50' S 144° 54.48' E, is temporarily unlit.

For further information contact Melbourne VTS on 9644 9700.


**Mariners are advised to navigate with additional caution when in the vicinity of South Channel Beacon 21.**

**Charts & Publications affected:** AUS 158

**Further notice:** Further notice will be issued.



**Andrew Hays  
Deputy Harbour Master**



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)  
 The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website  
[www.vicports.vic.gov.au](http://www.vicports.vic.gov.au)