

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 17 May 2018
Australia – Victoria

No. 177(T) - 2018

Local Port of Port Phillip

Patterson River

Patterson River Entrance-Fixed Port and Starboard Lateral Navigation Lights – Non-Operational for Maintenance.

Date: **Immediate.**

Details: Mariners are advised that fixed port and starboard lateral mark lights with characteristics port – Fl(3) R. 5s 5M and starboard Fl(3) G. 5s 6M, situated on the end of the Patterson River rock groin at approximate locations port 38 04.384S 145 07.178E (WGS84) starboard 38 04.424S 145 07.184E (WGS84), are temporarily not operational for maintenance works.

Mariners are advised to navigate with caution within the vicinity of Patterson River entrance.

Charts & Publications

Affected: AUS 143

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Victor Teoh
Senior Manager Local Ports and Waterways
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au or visit www.parks.vic.gov.au to view Notices.