

Melbourne, 3 August 2018

Australia – Victoria

No. 243 – 2018

PORT OF MELBOURNE

CHANGE TO HARBOUR MASTERS DIRECTIONS EDITION 10 AUGUST 2017

Date: 3 August 2018

Refers: N/A

Details: In accordance with sections 232(1)(b) and 232(1)(f) of the Marine Safety Act 2010 (Vic), I hereby give the following written directions:

The following change is effective with immediate effect.


3.17.7 Swanson Dock - restriction on the movement of vessels with beam > 32.5m

If a vessel with a beam >32.5 m moored on one side of Swanson Dock overlaps any part of a vessel with a beam >32.5 m moored on the opposite side of Swanson Dock, no other vessel with a beam >32.5 m is permitted to pass between the 2 moored vessels *except with the Harbour Master's express permission.*

**Charts &
Publications**

affected: Harbour Masters Directions Edition 10 August 2017

Further notice: No further notice will be issued



**Roy Stanbrook
Harbour Master**