

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 21 November 2018**  
**Australia – Victoria**

**No. 321 - 2018**

**Local Port of Port Phillip**

**Indented Head**  
**Governor Reef Channel - Installation of new aid to navigation buoys.**

**Date:** **Immediate**

**Details:** Mariners are advised of the establishment of a channel marked by x4 lit lateral buoys to facilitate safe navigation within the vicinity of Governor Reef, Indented Head.

Approximate locations (WGS84) and characteristics of the new aids are:

<i>Latitude</i>	<i>Longitude</i>	<i>Function</i>	<i>Light</i>
38°08.930'S	144°43.336'E	Port lateral buoy North	New – lit with characteristics Fl.R.3s
38°08.925'S	144°43.379'E	Starboard lateral buoy North	New – lit with characteristics Fl.G.3s
38°09.231'S	144°43.491'E	Port lateral buoy South	New – lit with characteristics Fl.R.3s
38°09.233'S	144°43.550'E	Starboard lateral buoy South	New – lit with characteristics Fl.G.3s

**Mariners are advised to exercise caution when navigating within the vicinity of Governor Reef and reminded the master of a vessel must not cause or allow the vessel to be anchored in the marked channel as per section 23B of the Victorian Vessel and Operating Zoning Rules.**

**Charts & Publications**

**Affected:** AUS 143 &157.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Victor Teoh  
Senior Manager Local Ports and Waterways  
Melbourne Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).